




## TPP “easy read” Measuring Device

### Measuring Accuracy



#### Measuring accuracy

Tool: Measuring gauge with an accuracy of  $\pm 0.01$  mm

Measurement point	Volume on scale $\mu$ l	Maximum Deviation from Nominal mm
1	5.0	$\pm 0.05$
2	3.5	$\pm 0.05$
3	0.7	$\pm 0.05$
4	0.3	$\pm 0.05$
5	0.0	$\pm 0.05$